



Deval L. Patrick
GOVERNOR

Timothy P. Murray
LIEUTENANT GOVERNOR

Commonwealth of Massachusetts
OFFICE OF CONSUMER AFFAIRS
DIVISION OF PROFESSIONAL LICENSURE
Office of Investigation

The Office of the Board of Examiners of
Plumbers and Gasfitters

1000 Washington Street Suite 710
Boston, Massachusetts 02118

BARBARA ANTHONY
UNDERSECRETARY, OFFICE OF
CONSUMER AFFAIRS & BUSINESS
REGULATION

GEORGE WEBER
DIRECTOR, DIVISION OF
PROFESSIONAL LICENSURE

JOSEPH A. PELUSO, JR.
EXECUTIVE DIRECTOR FOR THE
BOARD OF THE EXAMINERS OF
PLUMBERS AND GASFITTERS

CHRISTOPHER N. CARROLL
CHIEF INVESTIGATOR, OFFICE
OF INVESTIGATIONS

Enacted 4/7/10, amended 5/5/10

248 CMR 10.09(1)(a) requires interceptors and separators "to prevent the discharge of oil, gasoline, grease, sand, and other substances, that are harmful or hazardous to the building drainage system, the public sewer, or sewage treatment plant or other sewage treatment processes." It is the interpretation of the Board that such prevention is required for any building subject to the state plumbing code which utilizes garage or overhead doors sufficiently wide to allow the entrance of a truck or automobile. This interpretation does not apply to single family residential garages or exterior residential storage sheds that do not contain any plumbing and are not part of any other structure.

